


Driver DVD Revision History

20210525--> Add Win10-2019 driver

DRIVER DISC content

| Layer 1 | |
|--------------|----------|
| \API Package | Folder |
| \DRIVER | Folder |
| \USER MANUAL | Folder |
| README | PDF file |



| Layer 2 \API Package folder | |
|-----------------------------|---------|
| \DEMO PROJECT folder | Demo AP |
| \Prox API Standard folder | API |
| \Document folder | Guide |

| Layer 2 \DRIVER folder | | | | | | | | | | | |
|---------------------------|--|---------------------------|-------|----|-------|-----------|-----------------------|-------|----|-------|-----------------|
| \Flash BIOS folder | BIOS & Updating tool | | | | | | | | | | |
| \Platform folder | <p>Driver</p> <ol style="list-style-type: none"> The sequence of setup is, Main Chip => Hotfix => Graphics => Serial IO => Intel(R) TXE Package => LAN Chip => Sound Codec You will be prompted to reboot when installation is complete. <p>Main Chip /Intel® Apollo Lake</p> <table border="1"> <tbody> <tr> <td rowspan="2">Windows 10 IOT Enterprise</td> <td>32bit</td> <td>NA</td> </tr> <tr> <td>64bit</td> <td>10.1.1.38</td> </tr> <tr> <td rowspan="2">Windows 10 LTSC(2019)</td> <td>32bit</td> <td>NA</td> </tr> <tr> <td>64bit</td> <td>10.1.17968.8131</td> </tr> </tbody> </table> | Windows 10 IOT Enterprise | 32bit | NA | 64bit | 10.1.1.38 | Windows 10 LTSC(2019) | 32bit | NA | 64bit | 10.1.17968.8131 |
| Windows 10 IOT Enterprise | 32bit | | NA | | | | | | | | |
| | 64bit | 10.1.1.38 | | | | | | | | | |
| Windows 10 LTSC(2019) | 32bit | NA | | | | | | | | | |
| | 64bit | 10.1.17968.8131 | | | | | | | | | |

\Platform folder

Hotfix / Windows10 critical security update

| | | |
|---------------------------------|-------|-----------|
| Windows 10 IOT Enterprise(2016) | 32bit | NA |
| | 64bit | kb3211320 |
| | it | kb3213986 |

Graphics /Intel®HD

| | | |
|---------------------------|-------|----------------|
| Windows 10 IOT Enterprise | 32bit | NA |
| | 64bit | 21.20.16.4590 |
| Windows 10 LTSC(2019) | 32bit | NA |
| | 64bit | 26.20.100.6708 |

Serial IO /

| | | |
|---------------------------|-------|---------------|
| Windows 10 IOT Enterprise | 32bit | NA |
| | 64bit | 30.100.1631.3 |
| Windows 10 LTSC(2019) | 32bit | NA |
| | 64bit | 30.100.1631.3 |

Intel® TXE Package

| | | |
|---------------------------|-------|--|
| Windows 10 IOT Enterprise | 32bit | NA |
| | 64bit | 3.0.0.1115 |
| Windows 10 LTSC(2019) | 32bit | NA |
| | 64bit | APL-M 3.1.60.2280 APL-I 3.1.65.2288 |

LAN Chip/ INTEL I210

| | | |
|---------------------------|-------|-------------|
| Windows 10 IOT Enterprise | 32bit | NA |
| | 64bit | 12.15.184.0 |
| Windows 10 LTSC(2019) | 32bit | NA |
| | 64bit | 12.15.184.1 |

Sound Codec / Realtek ALC888S

| | | |
|---------------------------|-------|------------|
| Windows 10 IOT Enterprise | 32bit | NA |
| | 64bit | 6.0.1.8036 |
| Windows 10 LTSC(2019) | 32bit | NA |
| | 64bit | 6.0.1.8186 |

Layer 2 \DRIVER folder

\Device folder

Touch / eGalax Touch

| Main board version | | |
|---------------------------|-------|--------------|
| Windows 10 IOT Enterprise | 32bit | NA |
| | 64bit | 5.14.0.14916 |

WIFI module/ AJ-RTL-8812AEACC-01

| | | |
|---------------|-------|-----------|
| for Windows10 | 32bit | 3.00.0012 |
| | 64bit | 3.00.0012 |
| for Linux | | |
| | 64bit | V5.1.5 |

WIFI module/ ZQ802XRN7-01

| | | |
|---------------|-------|-----------------|
| for Windows10 | 32bit | NA |
| | 64bit | 2013.7.901.2014 |

4G / EC25-E

| | | |
|---------------|-------|--------|
| for Windows10 | 32bit | V1.0 |
| | 64bit | V1.0 |
| for Linux | 32bit | V1.3.0 |
| | 64bit | |

4G/ MPC1-L210

| | | |
|---------------|-------|----------|
| for Windows10 | 32bit | V1.0.1.6 |
| | 64bit | V1.0.1.6 |